

Message

---

**From:** Stoll, Pat [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=7DD5350984A64458AFF8A3CD4299A83C-STOLL, PATRICK W.]  
**Sent:** 10/18/2016 10:28:41 PM  
**To:** Bobby.Dye@deq.idaho.gov; Mollie.Mangerich@deq.idaho.gov  
**CC:** Michael.Simon@deq.idaho.gov; Steve.Bacom@deq.idaho.gov; Darrin.Pampaian@deq.idaho.gov; David.Anderson@deq.idaho.gov  
**Subject:** RE: Whiteside Dairy, Rupert Area

Many thanks to all of you!

---

**From:** Bobby.Dye@deq.idaho.gov [mailto:Bobby.Dye@deq.idaho.gov]  
**Sent:** Tuesday, October 18, 2016 11:49 AM  
**To:** Mollie.Mangerich@deq.idaho.gov  
**Cc:** Michael.Simon@deq.idaho.gov; Steve.Bacom@deq.idaho.gov; Darrin.Pampaian@deq.idaho.gov; Stoll, Pat <STOLL.PAT@epa.gov>; David.Anderson@deq.idaho.gov  
**Subject:** RE: Whiteside Dairy, Rupert Area

Mollie,

Good morning. Yes, I will ensure we keep Pat informed.

Bobby

---

**From:** Mollie Mangerich  
**Sent:** Tuesday, October 18, 2016 11:44 AM  
**To:** Bobby Dye  
**Cc:** Michael Simon; Steve Bacom; Darrin Pampaian; Stoll, Pat; Mollie Mangerich  
**Subject:** RE: Whiteside Dairy, Rupert Area

Hi Bobby,

If you contact work with the property owner would you please keep Pat Stoll, EPA in the loop as an FYI?

Thanks all,

Mollie Mangerich  
Solid Waste Program Manager  
Waste Management and Remediation Division  
Idaho Department of Environmental Quality  
1410 North Hilton  
Boise, ID 83706  
phone: 208-373-0121  
fax: 208-373-0154  
[Mollie.Mangerich@deq.idaho.gov](mailto:Mollie.Mangerich@deq.idaho.gov)

---

**From:** Michael Simon  
**Sent:** Tuesday, October 18, 2016 10:56 AM  
**To:** Mollie Mangerich; Darrin Pampaian  
**Cc:** Steve Bacom; Bobby Dye  
**Subject:** RE: Whiteside Dairy, Rupert Area

I was out yesterday so coming in late on this. This looks to me to be a decommissioning issue the owner never took care of at the time of shut down. It is both an odor issue as well as a safety issue for the owner of the property. I assume Bobby Dye is already aware of this but perhaps having DEQ contact the property owner to resolve the odor could help facilitate them to clean out the digesters

---

**From:** Mollie Mangerich  
**Sent:** Tuesday, October 18, 2016 9:22 AM  
**To:** Darrin Pampaian  
**Cc:** Michael Simon  
**Subject:** RE: Whiteside Dairy, Rupert Area

Thank you Darrin, appreciate that.

Mollie Mangerich  
Solid Waste Program Manager  
Waste Management and Remediation Division  
Idaho Department of Environmental Quality  
1410 North Hilton  
Boise, ID 83706  
phone: 208-373-0121  
fax: 208-373-0154  
[Mollie.Mangerich@deq.idaho.gov](mailto:Mollie.Mangerich@deq.idaho.gov)

---

**From:** Darrin Pampaian  
**Sent:** Tuesday, October 18, 2016 7:10 AM  
**To:** Mollie Mangerich  
**Cc:** Michael Simon  
**Subject:** RE: Whiteside Dairy, Rupert Area

Mollie,

A quick point of clarification. The facility has a Permit by Rule for the dairy implementing Best Management Practices, they have no air permit for the methane production operation.

Darrin Pampaian

---

**From:** Mollie Mangerich  
**Sent:** Monday, October 17, 2016 5:56 PM  
**To:** Michael McCurdy; Michael Simon; Darrin Pampaian; Larry Waters; David Anderson  
**Cc:** Barry Burnell; Tiffany Floyd; Stoll, Pat; Mollie Mangerich  
**Subject:** Whiteside Dairy, Rupert Area  
**Importance:** High

I received a call from Pat Stoll, EPA ID Operations Office. [Stoll.Pat@epa.gov](mailto:Stoll.Pat@epa.gov)  
He received a complaint (individual wished to remain anonymous) today about an old methane production facility located at the Whitesides Dairy, Rupert, ID. (AQ Permit Number : PR-060423; effective 7/12/06)

The complainant spoke to concern over a shuttered methane (anaerobic digestion) production facility that was shut down at the dairy about 6-7 years ago after the business venture went bankrupt.  
<http://www.hcn.org/issues/346/17006> (the article identifies "[Intrepid Technology and Resources Inc.](#)" out of Idaho Falls).

The bankruptcy left 10 methane digesters on site, described as the older style (tall, vertical), that left all source material in the tanks – and they are generating pressure and starting to bulge.

**Ex. 6 PP / Ex. 7(C)/ 7(D)**

# Ex. 6 PP / Ex. 7(C)/ 7(D)

Pat has spoken with Marv Patten, Bureau Chief, ISDA who noted this was out of ISDA's regulatory authority, but offered his assistance where appropriate.

Pat is hoping that DEQ can provide assistance in problem-solving this situation.

Thanks,

Mollie Mangerich  
Solid Waste Program Manager  
Waste Management and Remediation Division  
Idaho Department of Environmental Quality  
1410 North Hilton  
Boise, ID 83706  
phone: 208-373-0121  
fax: 208-373-0154  
[Mollie.Mangerich@deq.idaho.gov](mailto:Mollie.Mangerich@deq.idaho.gov)